


**BUILDING SAFETY REPORT**

Name of School: - **Shaheed Udham Singh Academyat Vill. Satauj Tehsil Sunam Distt. Sangrur.**

Our Department Technical team has visited the above mentioned school building along with School authorities and have visually inspected. The Building seems to be visually safe subject to the following observation & conditions.

- a) Parameters to check the stability and safety of building such as bearing capacity report, Structural Drawings, Test Reports of Material used Quality Control reports and certificates from Engineer in Charge for construction are not available.
- b) In case of any addition, alteration or expansion and modification to this building are done; certificate may be re-obtained after completion from undersigned.
- c) In case the building is affected by flood or if there is settlement of walls/foundation or sagging of roofs etc., immediate inspection of the undersigned be arranged to check the stability and safety of the building.
- d) A separate certificate regarding Fire Fighting should be obtained from the component authority.
- e) The owner of the building/Management is fully responsible regarding safety of building from all angles in spite of this report.
- f) This report is not valid for legal purpose.
- g) This building visually seems safe to occupy for the normal use up to **March, 2024**

  
Executive Engineer, 11/x  
Panchayati Raj P.W. (C&M) Division,  
Sangrur.