Part-II

Building Safety Report

Name of School: Shaheed Udham Singh Academy Satauj. Distt. Sangrur.

Sh. Shubham Goyal (Junior Engineer) has visited the above mentioned school on dated 25.08.2026 and on his visual inspection; the building seems to be safe subject to the following observation & conditions.

a) Parameters to check the stability and safety of building as Architectural Drawings, Bearing capacity, Foundation detail, Structural Drawings, Technical Specifications, Test Reports of Material used, Quality Control reports and certificate from the Engineer in-Charge for construction are not available.

b) In case any addition, alteration or expansion and modification to this building are done certificate may be obtained after the completion from the undersigned.

c) In case the building is affected by flood or if there is any settlement of walls/ foundation or sagging of roofs etc. immediate inspection of the undersigned be arranged to check stability and safety of the building.

d) This Certificate holds validity only with valid Fire Safety Certificate. A separate certificate regarding Fire Fighting should be obtained from the competent Authority & **it will be your personal responsibility to extend the period of the said fire safety certificate upto and after extending the period, this office should be informed , failing which the building safety certificate issued by this office will be considered cancelled with immediate effect.**

e) A separate certificate regarding Electrical works should be obtained from the competent Authority.

f) The owner of the building / Management is fully responsible regarding safety of the building from all angles in spite of the report.

g) The covered area of the building is As per Drawings Sft.

h) The report is not valid for legal purpose.

i) The building visually seems safe to occupy for normal use to **One Year, upto** 31-03-2027

(Shubham Goyal)
J.E

Sub Divisional Engineer
Provincial Sub Div. PWD, B&R
Sunam